WHEN TO CONDUCT QUARTERLY VISUAL MONITORING

★ ONCE EVERY QUARTER

- January 1- March 31
- April 1- June 30
- July 1 September 30
- October 1 December 31

★ DURING A QUALIFYING RAIN EVENT

- Precipitation, ice or snow melt that produces a measurable discharge at an outfall that occurs at least 72 hours from a previous qualifying storm event.
- Check outfall every 15 minutes after rain starts to determine when runoff begins.

★ WITHIN THE FIRST 60 MINUTES to 2.25 HOURS

- From each outfall. Pour sample into a 1L Imhoff cone and fill out form.
- Let sit and let sit1 hour before filling out the section on settled solids.

WHEN TO CONDUCT QUARTERLY VISUAL MONITORING

★ ONCE EVERY QUARTER

- January 1- March 31
- April 1- June 30
- July 1 September 30
- October 1 December 31

★ DURING A QUALIFYING RAIN EVENT

- Precipitation, ice or snow melt that produces a measurable discharge at an outfall that occurs at least 72 hours from a previous qualifying storm event.
- Check outfall every 15 minutes after rain starts to determine when runoff begins.

★ WITHIN THE FIRST 60 MINUTES to 2.25 HOURS

- From each outfall. Pour sample into a 1L Imhoff cone and fill out form.
- Let sit and let sit1 hour before filling out the section on settled solids.